CERTIFICATE OF COMPLIANCE

 Certificate Number
 20170728-MH48087

 Report Reference
 MH48087-20141210

Issue Date 2017-July-28

Issued to: RED WING SHOE CO.

314 MAIN ST

RED WING, MN 55066

This is to certify that representative samples of

PROTECTIVE CLOTHING FOR PROTECTION OF INDUSTRIAL PERSONNEL AGAINST FLASH FIRE

See Addendum Page.

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: NFPA 2112, Flame-Resistant Garments for Protection of

Industrial Personnel Against Flash Fire, 2012 Edition


Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.





UL LLC





CERTIFICATE OF COMPLIANCE

 Certificate Number
 20170728-MH48087

 Report Reference
 MH48087-20141210

 Income Parts
 2017, July 28

Issue Date 2017-July-28

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

PROTECTIVE CLOTHING FOR PROTECTION OF INDUSTRIAL PERSONNEL AGAINST FLASH FIRE

Garment Type	Pattern (Model)	UL ID
Shirt	663	48087040101
Jacket	620	48087040102
Lab Coat	628	48087040103
Trouser	661, 664	48087040104
Coverall	600, 601, 606, 607, 608, 609, 701, 735	48087040105
Bib Coverall	640	48087040106
Insulated Coverall	602	48087040107
Insulated Jacket	629	48087040108
Insulated Bib Coverall	641	48087040109
Insulated Parka	624	480870401010
Jean	665	480870401011

Manufacturing Location: Safety Offshore of Mexico SA de C.V.

NOTE: The garments also contain a five digit Style Designation which describes the various construction features incorporated in the garment.

Ba Milly

Bruce Mahrenholz Director North

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

